

# Fall-off Survey = FOS

**Synonym:** [Fall-off Survey \(FOS\)](#) = [Fall-off test \(FOT\)](#)

[Pressure transient survey](#) in [injector](#) during the pressure drop period caused by shutting well down or reducing its injection rate.

## See Also

---

[Petroleum Industry](#) / [Upstream](#) / [Subsurface E&P Disciplines](#) / [Well Testing](#) / [Pressure Testing](#)

[ [Well & Reservoir Surveillance](#) ] [ [Pressure Transient Analysis \(PTA\)](#) ]