

Fall-off test = FOT

Synonym: [Fall-off Survey \(FOS\)](#) = [Fall-off test \(FOT\)](#)

[Pressure transient survey](#) in [injector](#) during the pressure drop period caused by shutting well down or reducing its injection rate.

See Also

[Petroleum Industry](#) / [Upstream](#) / [Subsurface E&P Disciplines](#) / [Well Testing](#) / [Pressure Testing](#)

[[Well & Reservoir Surveillance](#)] [[Pressure Transient Analysis \(PTA\)](#)]